



**AUDI A3 SPORTBACK: 1LKX533**

Vinnumber:	<b>WAUZZZ8VXGA059737</b>	Versionname:	<b>1.6 TDI 81KW ATTRACTION</b>
First Registrationdate:	<b>15/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>103027</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4820</b>
Maintenance:	<b>15000KM OF 509DGN</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1335,23</b>
Grill frame, Broken, E - Replace	<b>316,30</b>



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Moulding windscreen L, Scratch(es), E - Replace 23,60



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Door R L, Dent(s), Acceptable 0,00



Ignition key, Missing, E - Replace 150,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80





Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Door F R, Chemical polution, LI - Repair and paint (complete)	318,35
---	--------



Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*