



**AUDI A1 SPORTBACK: 1TLK738**

Vinnumber:	<b>WAUZZZ8X9JB045752</b>	Versionname:	<b>1.0 TFSI ultra 60kW</b>
First Registrationdate:	<b>7/12/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>10262</b>	Power Kw:	<b>60</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4621</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Luggage cover	
GPS storage		Rear parking sensors	
GPS storage	<b>SD</b>	Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/60/15/84 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>	Jack	<b>Yes</b>
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>655,14</b>
Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>169,44</b>



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Dent(s), PDR - Paintless dent repair 63,00




Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Chemical polution, LI - Repair and paint (complete) 246,56



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 176,14



Roof, Dent(s), Acceptable 0,00

No pictures to display