



**BMW 3 GRAN TURISMO: 1SCP989**

|                                    |                          |              |                      |
|------------------------------------|--------------------------|--------------|----------------------|
| Vinnumber:                         | <b>WBA8T11010BF25555</b> | Versionname: | <b>318d (100 kW)</b> |
| First Registrationdate:            | <b>10/04/2017</b>        | Fiscalpower: |                      |
| Expertise Mileage:                 | <b>68367</b>             | Power Kw:    | <b>100</b>           |
| Bodytype:                          |                          | Body color:  | <b>Dark Grey</b>     |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>       |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>     |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>            |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1709</b>          |
| Number of doors:                   | <b>5</b>                 |              |                      |
| Number of seats:                   | <b>5</b>                 |              |                      |
| Number head rests:                 | <b>5</b>                 |              |                      |
| Rims summer:                       | <b>Aluminium</b>         |              |                      |
| Category:                          | <b>Passenger Car</b>     |              |                      |
| Oil level:                         | <b>OK</b>                |              |                      |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                      |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Central consol F      |                   |
| GPS storage                    | <b>HD</b>                    | Luggage cover         |                   |
| GPS storage                    |                              | Front parking sensors |                   |
| Windows electric F             |                              | Rear parking sensors  |                   |
| Windows electric R             |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Cruise Control                 |                              |                       |                   |
| Steering wheel multifunctional |                              |                       |                   |
| Radio multimedia               |                              |                       |                   |
| Type of headlighting           | <b>Headlighting LED</b>      |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining leather</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>225/55/17/97 W LightMetal</b> |       |                          |       |                          |
| Summer tyres:                    | Fr.L. | <b>Continental: 6 mm</b> | Fr.R. | <b>Continental: 6 mm</b> |
|                                  | Re.L. | <b>Continental: 4 mm</b> | Re.R. | <b>Continental: 4 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|   |                |
|---|----------------|
| <b>Total cost ex VAT</b>  | <b>1744,54</b> |
| <b>Alloy rim F L, Scratch(es), LI - Repair and paint (complete)</b> | <b>95,00</b>   |



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete) 115,56



Sill outer R, Scratch(es), LI - Repair and paint (complete) 310,50



Door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door panel R R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 301,68



Door R R, Dent(s) and scratch(es), Acceptable 0,00

Door R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror basis L, Scratch(es), Acceptable

0,00

No pictures to display