



BMW 2 GRAN TOURER: 1LFN899

Vinnumber:	WBA2E310305C00237	Versionname:	1.5 216D GRAN TOURER
First Registrationdate:	15/09/2015	Fiscalpower:	
Expertise Mileage:	78620	Power Kw:	85
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 23000 KM	Parking lot:	2612
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Hankook: 4 mm	Fr.R.	Hankook: 4 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1696,65

Engine protective plate, Chemical polution, E - Replace 110,50



Tyre F R, Deformed / Strained, E - Replace 132,00



Door R R, Bad repair, LI - Repair and paint (complete) 318,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Repaired, P - Check 0,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 235,80





Wing R R, Bad repair, LI - Repair and paint (complete)

308,20



Wing F R, Chemical polution, 67 - Polish

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Stone chip(s), Acceptable 0,00

