



BMW 3: 1HTP578

Vinnumber:	WBA3K11090F835715	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	30/09/2014	Fiscalpower:	
Expertise Mileage:	130272	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	1324
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1403,18
-------------------	----------------

Window F R door, Scratch(es), E - Replace	0,00
---	-------------



Bumper F L, Scratch(es), It - Spot repair

115,56



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Maintenance, Maintenance, Execute

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), Le - Replace and paint

651,00



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Sill outer L, Scratch(es), LI - Repair and paint (complete)

310,50



Rear window, Scratch(es), E - Replace

0,00

