



**OPEL Vivaro 2900: 1GTN737**

Vinnumber:	<b>WOLF7B1B1EV610892</b>	Versionname:	<b>VIVARO 2900 B/F MWB L2H1 DPF(EU5) 115PK</b>
First Registrationdate:	<b>25/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>110374</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4415</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/65/16/107 T Steel</b>				
Summer tyres:	Fr.L.	<b>Michelin: 9 mm</b>	Fr.R.	<b>Michelin: 9 mm</b>
	Re.L.	<b>Michelin: 9 mm</b>	Re.R.	<b>Michelin: 9 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	<b>791,67</b>
-------------------	---------------

Trunk door R L, Dent(s) and scratch(es), It - Spot repair	<b>115,56</b>
---	---------------



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>231,15</b>
---	---------------




Bumper R, Scratch(es), E - Replace

329,40



Door R L, Dent(s), It - Spot repair

115,56



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Bodywork, Not original part, Acceptable

0,00

No pictures to display