



**AUDI A4 AVANT: 1LFT574**

Vinnumber:	<b>WAUZZZ8K5FA166747</b>	Versionname:	<b>2.0 TDI ULTRA 100KW</b>
First Registrationdate:	<b>16/09/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>72958</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1708</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	<b>No Tow bar</b>
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/50/17/94 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>
Total cost ex VAT	<b>2540,22</b>
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Wing R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing F R, Deformed / Strained, Le - Replace and paint

530,02



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing F L, Deformed / Strained, Le - Replace and paint

530,02



Door R R, Dent(s), Acceptable

0,00

*No pictures to display*

Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

