



**MERCEDES CLA SHOOTING BRAKE: 1KVB750**

Vinnumber:	<b>WDD1179081N252227</b>	Versionname:	<b>2.1 CLA 200 CDI URBAN SHOOTING BRAKE</b>
First Registrationdate:	<b>10/07/2015</b>	Fiscalpower:	<b>100</b>
Expertise Mileage:	<b>113168</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OVER 324 DAGEN</b>	Parking lot:	<b>2711</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>1</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>SD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/45/17/91 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Yokohama: 2 mm</b>	Fr.R.	<b>Yokohama: 2 mm</b>
	Re.L.	<b>Yokohama: 2 mm</b>	Re.R.	<b>Yokohama: 2 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>190,00</b>
-------------------	---------------

Rocker panel inner R L, Dent(s), Acceptable	<b>0,00</b>
---	-------------

*No pictures to display*

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
---	--------------



Trunk lid covering R, Scratch(es), Acceptable 0,00

*No pictures to display*

Boot carpet, Stain, Acceptable 0,00

*No pictures to display*

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), Acceptable 0,00

*No pictures to display*