



FIAT 500: 1VMN339

| | | | |
|------------------------------------|--------------------------|--------------|----------------|
| Vinnumber: | ZFA3120000JB22942 | Versionname: | |
| First Registrationdate: | 2/01/2019 | Fiscalpower: | |
| Expertise Mileage: | 19 | Power Kw: | 51 |
| Bodytype: | Hatchback | Body color: | Black |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Steel |
| Fueltype: | Petrol | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3515 |
| Number of doors: | 3 | | |
| Number of seats: | 4 | | |
| Number head rests: | 4 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|-----------------------------|----------------------|-------------------|
| Windows electric F | | Luggage cover | |
| Steering wheel multifunctional | | Rear parking sensors | |
| Radio multimedia | | Type of Tow bar | No Tow bar |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | No GPS | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | No climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------|-------|--------------------|-------|--------------------|
| 175/65/14/82 T Steel | | | | |
| Summer tyres: | Fr.L. | Other: 7 mm | Fr.R. | Other: 7 mm |
| | Re.L. | Other: 7 mm | Re.R. | Other: 7 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|------|
| Total cost ex VAT | 0,00 |
|-------------------|------|

| | |
|---------------------------------|------|
| Bodywork, No damage, Acceptable | 0,00 |
|---------------------------------|------|

No pictures to display