



BMW 5: 1GDC586

Vinnumber:	WBA5J51000D580595	Versionname:	5 TOURING 520dXA 163PK Aut.
First Registrationdate:	6/01/2014	Fiscalpower:	
Expertise Mileage:	78529	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3628
Maintenance:	SINDS 3200 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Seats electric F L
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	1713,75
-------------------	----------------

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	---------------



Door F R, Dent(s), LI - Repair and paint (complete) 430,02



Wing R R, Scratch(es), It - Spot repair 115,56




Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (partial) 264,21



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror basis L, Scratch(es), Smart repair 110,64



Maintenance, Maintenance, Execute 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

