



**FORD Mondeo: 1HTP577**

Vinnumber:	<b>WF0GXXG8BBGE887920</b>	Versionname:	<b>MONDEO CLIP EConet.Titanium Style 115PK</b>
First Registrationdate:	<b>30/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>109730</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>CONTROLLEREN</b>	Parking lot:	<b>1514</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Adaptive cruise control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/60/16/99 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Uniroyal: 6 mm</b>	Fr.R.	<b>Uniroyal: 6 mm</b>
	Re.L.	<b>Uniroyal: 4 mm</b>	Re.R.	<b>Uniroyal: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>2245,41</b>
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

307,80



Rear window, Scratch(es), E - Replace

0,00



Door R L, Bad repair, LI - Repair and paint (complete)

318,35



Floor covering F L, Tear, E - Replace

252,00

No pictures to display

Door F R, Bad repair, LI - Repair and paint (complete)

318,35



Door F L, Scratch(es), It - Spot repair

115,56



Bumper R, Bad repair, LI - Repair and paint (complete)

211,80



Door R R, Bad repair, LI - Repair and paint (complete)

318,35



Wing R R, Bad repair, LI - Repair and paint (complete)

308,20

