


BMW 5 TOURING: 1LJR065

Vinnumber:	WBA5L31030G120974	Versionname:	2.0 520D (120KW) TOURING
First Registrationdate:	6/10/2015	Fiscalpower:	
Expertise Mileage:	150658	Power Kw:	120
Bodytype:		Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3610
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/101 W LightMetal			
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1500,34
--------------------------	----------------

Wing R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door F L, Scratch(es), Acceptable 0,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Rear window, Scratch(es), E - Replace 420,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16





Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Rearview mirror basis L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display