



**AUDI Q7: 1TAU166**

Vinnumber:	<b>WAUZZ4M2JD011507</b>	Versionname:	<b>ultra 3.0 TDI 155kW Tiptr. quattro</b>
First Registrationdate:	<b>7/09/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>100021</b>	Power Kw:	<b>155</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3225</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F		Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Sun Roof electric	
Seats F heated		Panoramic roof	
Radio multimedia		Central consol F	
Type of headlighting	<b>Headlighting LED</b>	Luggage cover	
Type of GPS	<b>GPS big screen color</b>	Front parking sensors	
Type of Lining	<b>Lining leather</b>	Rear parking sensors	
Type of climate control	<b>Manual climate control</b>	Type of Tow bar	<b>No Tow bar</b>
Sport seats			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>285/45/20/112 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Pirelli: 7 mm</b>	Fr.R.	<b>Pirelli: 7 mm</b>
	Re.L.	<b>Pirelli: 3 mm</b>	Re.R.	<b>Pirelli: 3 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>340,00</b>
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>



Ignition key, Missing, E - Replace

150,00



Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00

