



BMW 4 GRAN COUPE: 1LJR748

Vinnumber:	WBA4E71040GS99748	Versionname:	2.0 418D (110KW) GRAN COUPE
First Registrationdate:	6/10/2015	Fiscalpower:	
Expertise Mileage:	127643	Power Kw:	110
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2621
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/18/91 V LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	2612,51
Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16



Alloy rim R R, Deformed / Strained, E - Replace 277,44



Bonnet, Chemical pollution, LI - Repair and paint (complete) 348,09



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s), LI - Repair and paint (complete) 254,16



Roof, Chemical pollution, LI - Repair and paint (complete) 577,80



Protection plate M, Hole, E - Replace 74,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Crack, LI - Repair and paint (complete) 362,02



Engine, Not functioning (well), Diagnosis 0,00

No pictures to display

Wing R R, Chemical pollution, LI - Repair and paint (complete) 369,84

