


**IVECO Daily 40C15: 1DLL209**

Vinnumber:	<b>ZCFC40A5005901252</b>	Versionname:	<b>DAILY CH2C 40C15 146PK 3500KG</b>
First Registrationdate:	<b>15/06/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>145237</b>	Power Kw:	<b>107</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV20</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F			
Cruise Control			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>No climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/75/15/105 R Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	449,20
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Boot carpet, Damaged, E - Replace	123,00



Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Headlight R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Ignition key, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Smart repair	110,64



Wing F R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Dashboard, Hole, Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sidewall FR (LCV), Dent(s) and scratch(es), It - Spot repair	115,56



Interior, Dirty, Cleaning	100,00
---------------------------	--------

