



FORD TRANSIT COURIER: KL6288

Vinnumber:	WF0WXXTACWFT78032	Versionname:	1.5 TDCI 56KW TREND
First Registrationdate:	10/09/2015	Fiscalpower:	
Expertise Mileage:	236100	Power Kw:	55
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3203
Number of doors:	6		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Central consol F
GPS storage	Type of Tow bar
GPS storage	SD
Windows electric F	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/60/15/88 V Steel			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1532,76
Roof, Dent(s) and scratch(es), Acceptable	0,00





Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Trunk door R L, Dent(s) and scratch(es), It - Spot repair 115,56



Ignition key, Broken, E - Replace 150,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Gear shift lever knob, Broken, E - Replace 91,50



Floor covering F L, Hole, E - Replace 237,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair 58,80



Roof pillar L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace 22,50



Trunk door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 22,50



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 22,50



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Seat adjuster F L, Broken, E - Replace 9,00



Bumper F, Broken, E - Replace 398,40



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Moulding windscreen R, Missing, E - Replace 15,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 158,85

