


PEUGEOT 2008: QK7456

Vinnumber:	VF3CUBHY6FY114750	Versionname:	1.6 BLUEHDI 74KW S/S STYLE
First Registrationdate:	27/10/2015	Fiscalpower:	
Expertise Mileage:	198257	Power Kw:	74
Bodytype:		Body color	Light Red
Gearbox:	MAN 5 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2623
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/60/16/89 H LightMetal			
Winter tyres:	Fr.L.	Nokian: 5 mm	Fr.R.	Nokian: 5 mm
	Re.L.	Nokian: 4 mm	Re.R.	Nokian: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	925,49
Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35




Outer door handle F L, Scratch(es), Acceptable	0,00
No pictures to display	
Aerial, Strained , E - Replace	15,00



Alloy rim R R polished, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Smart repair	110,64



Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R polished, Scratch(es), Acceptable	0,00
No pictures to display	
Tailgate, Scratch(es), Acceptable	0,00



Bumper corner R L, Scratch(es), Acceptable	0,00
No pictures to display	
Roof, Chemical polution, LI - Repair and paint (complete)	481,50



Bonnet, Dent(s), Acceptable	0,00
No pictures to display	