

OPEL ASTRA SPORTS TOURER: 1NDU764

Vinnumber:	WOLPE8E60G8050564	Versionname:	1.6 CDTI 81kW ecoFLEX S/S Ultim. Pl. Ed
First Registrationdate:	1/02/2016	Fiscalpower:	
Expertise Mileage:	151823	Power Kw:	81
Bodytype:	Break	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2329
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/60/16/95 V LightMetal			
	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment


Spare wheel	Yes
-------------	------------

Total cost ex VAT	630,80
Door R R, Scratch(es), 67 - Polish	0,00
No pictures to display	
Dashboard, Glue residues, Cleaning	25,00



Bonnet, Bad repair, Acceptable

0,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Trunk lid covering R, Broken, E - Replace

124,30




Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Seat cover F R, Stain, Acceptable

0,00

No pictures to display

Seat cover F L, Worn, Acceptable

0,00

No pictures to display

Roof pillar R, Dent(s), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display