



OPEL Astra: 1HYE890

Vinnumber:	W0LPE6E64FG012991	Versionname:	ASTRA BER ecoFLEX Cosmo Star St/St 110PK
First Registrationdate:	28/10/2014	Fiscalpower:	
Expertise Mileage:	58031	Power Kw:	81
Bodytype:	Hatchback	Body color	Dark Brown
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2607
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Emergency spare wheel	Yes
-----------------------	-----

Total cost ex VAT	1713,76
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35



Wing F R, Chemical polution, LI - Repair and paint (complete)

220,18



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Interior, Dirty, Cleaning

0,00



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Bumper grille, Broken, E - Replace

32,40



Bumper moulding F M, Broken, E - Replace

14,40

