


MERCEDES GLA: 1JJR494

Vinnumber:	WDC1569081J074328	Versionname:	GLA 200 CDI 136PK
First Registrationdate:	6/01/2015	Fiscalpower:	
Expertise Mileage:	171636	Power Kw:	100
Bodytype:		Body color	GRIJS
Gearbox:	MAN 6 VIT	Body color	Dark Grey
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	OK	Oil level	OK
Maintenance	5800 KM	Parking lot	3703
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	1		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Manual climate control	
Adaptive cruise control		
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/60/17/96 V LightMetal			
	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Wing F R, Scratch(es), LI - Repair and paint (complete)		220,18
 		
Bumper F, Scratch(es), LI - Repair and paint (complete)		211,80
 		
Bumper R, Scratch(es), Acceptable		0,00
No pictures to display		
Door R L, Scratch(es), Acceptable		0,00
No pictures to display		
Door R R, Scratch(es), Acceptable		0,00
No pictures to display		
Wing moulding F R, Scratch(es), E - Replace		14,40
 		
Door F R, Scratch(es), Acceptable		0,00
No pictures to display		
Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)		115,56
 		
Door F L, Scratch(es), Acceptable		0,00
No pictures to display		
Windscreen, Bad repair, E - Replace		487,20
   		