



RENAULT CLIO: EM5029			
Vinnumber:	VF15RBF0A53792524	Versionname:	1.5 DCI 75 BUSINESS
First Registrationdate:	5/10/2015	Fiscalpower:	
Expertise Mileage:	118199	Power Kw:	55
Bodytype:	Hatchback	Body color	White
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4427
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options			
Windows electric F		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	185/65/15/88 T Steel			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment	
Repair kit	No
Compressor	No
Total cost ex VAT	931,98
Compressor, Missing, E - Replace	0,00
No pictures to display	
Wheel cover F L, Missing, E - Replace	24,00



Bonnet, Dent(s), Acceptable	0.00
-----------------------------	------

Dent(s), Dent(s), Replace		0,00
No pictures to display		
Rocker panel inner F L, Dent(s), LI - Repair and paint (complete)		115,56
		
Seat cover F L, Damaged, E - Replace		312,00
		
Wheel cover R L, Scratch(es), Acceptable		0,00
No pictures to display		
Backrest cover F L, Damaged, E - Replace		312,00
		
Tyre repair kit, Missing, E - Replace		168,42
		
Wheel cover R R, Scratch(es), Acceptable		0,00
No pictures to display		