


OPEL ASTRA: 1KHD760

Vinnumber:	W0LPD6EA3FG069626	Versionname:	1.3 CDTI ECOFLEX S/S ULTIMATE EDITION
First Registrationdate:	4/05/2015	Fiscalpower:	
Expertise Mileage:	79471	Power Kw:	70
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4428
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/60/16/95 V Steel			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	00		

Total cost ex VAT	799,85
-------------------	--------

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

wing F R, Scratch(es), Acceptable	0,00
No pictures to display	
Roof, Chemical polution, LI - Repair and paint (complete)	481,50
	
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	