



OPEL ASTRA SPORTS TOURER: 1LGF451

Vinnumber:	W0LPD8E6XG8004887	Versionname:	1.6 CDTI 81KW ECOFLEX S/S ULTIMATE EDITI
First Registrationdate:	21/09/2015	Fiscalpower:	
Expertise Mileage:	82192	Power Kw:	81
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3206
Maintenance	73 PROCENT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Luggage cover
GPS storage	Rear parking sensors
GPS storage	HD
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 H Steel			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Total cost ex VAT	32,40
-------------------	-------

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display	
------------------------	--

Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	------

No pictures to display	
------------------------	--

Outer door handle F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display	
------------------------	--

No pictures to display	
Trunk lid covering R, Scratch(es), Acceptable	0,00
No pictures to display	
Door frame F R, Scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Repaired, Acceptable	0,00
No pictures to display	
Door R L, Repaired, Acceptable	0,00
No pictures to display	
Door F L, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Tires, Not original part, Acceptable	0,00
No pictures to display	
Wing R R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Wheel cover R R, Scratch(es), Acceptable	0,00
No pictures to display	
Door frame F L, Scratch(es), Acceptable	0,00
No pictures to display	
MOT Certificate, Missing, Acceptable	0,00



Bumper grille, Broken, E - Replace	32,40
------------------------------------	-------

