


MERCEDES CLA SHOOTING BRAKE: 1LBX928

Vinnumber:	WDD1179081N258476	Versionname:	2.1 CLA 200 CDI SHOOTING BRAKE
First Registrationdate:	14/08/2015	Fiscalpower:	
Expertise Mileage:	99293	Power Kw:	100
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 12000 KM	Parking lot:	2821
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/94 V LightMetal			
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			425,00
Internal Boot Lining R, Scratch(es), Acceptable			0,00



Alloy rim F R, Scratch(es), I - Repair

100,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Repaired, P - Check

0,00



Internal Boot Lining L, Scratch(es), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Door frame R L, Dent(s), Acceptable

0,00

No pictures to display

Door panel F R, Scratch(es), Acceptable

0,00



Door F R, Repaired, P - Check

0,00



Door panel R R, Scratch(es), Acceptable

0,00



Door R R, Repaired, P - Check

0,00



Door R R, Dent(s), Acceptable

0,00

No pictures to display

Bodywork, Glue residues, Remove lettering

25,00



Alloy rim R R, Scratch(es), I - Repair

100,00



Alloy rim R L, Scratch(es), I - Repair

100,00



Alloy rim F L, Scratch(es), I - Repair

100,00



Door panel R L, Scratch(es), Acceptable

0,00



