



VOLKSWAGEN Caddy: 1FPQ752

Vinnumber:	WV2ZZZ2KZEX034497	Versionname:	CADDY MAXI LIFE 2PLC 4M Comfortl.110PK
First Registrationdate:	17/09/2013	Fiscalpower:	
Expertise Mileage:	174507	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3526
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/96 V LightMetal				
Summer tyres:	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Semperit: 6 mm	Re.R.	Semperit: 6 mm

Assistance equipment

Total cost ex VAT	848,25
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00





Interior, Dirty, Cleaning

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

95,00



Trunk lid covering R, Scratch(es), Smart repair

110,64



Door R L, Scratch(es), LI - Repair and paint (complete)

238,76



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Door F R, Dent(s), Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

150,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

158,85

