



AUDI A3 SPORTBACK: 1PAY318

Vinnumber:	WAUZZZ8V3GA120426	Versionname:	1.6 TDI 81KW ATTRACTION
First Registrationdate:	25/05/2016	Fiscalpower:	
Expertise Mileage:	66515	Power Kw:	81
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1431
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0	Jack	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1724,50
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bad repair, Acceptable 0,00




Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display


Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Rear window, Scratch(es), E - Replace 370,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Floor covering F L, Hole, Smart repair 64,32



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Door F L, Scratch(es), Acceptable 0,00

No pictures to display