



LU Volkswagen Golf: VK7628

Vinnnumber:	WVWZZZAUZJP035776	Versionname:	1.5 TSI 110kW Highline
First Registrationdate:	13/10/2017	Fiscalpower:	
Expertise Mileage:	26885	Power Kw:	110
Bodytype:		Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Petrol	Oil level	OK
Maintenance	3.200 KM OU 10 JOURS	Parking lot	3301
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			211,80
Door R L, Scratch(es), Acceptable			0,00
No pictures to display			
Alloy rim F L polished, Scratch(es), Acceptable			0,00
No pictures to display			
Tailgate, Scratch(es), Acceptable			0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display