



VOLVO XC60: 1LLB124

Vinnumber:	VV1DZARC1G2846855	Versionname:	2.0 D3 2WD SUMMUM
First Registrationdate:	16/10/2015	Fiscalpower:	
Expertise Mileage:	66975	Power Kw:	110
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1332
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Type of Tow bar
Type of GPS	Headlighting Xenon
Type of Lining	GPS big screen color
Type of climate control	Lining leather
	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	235/60/18/3 V LightMetal			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	00		

Total cost ex VAT	1281,95
Boot carpet, Dirty, Chemical cleaning	50,00




Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Door panel R L, Tear, E - Replace	132,00
-----------------------------------	--------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09
---	--------

