



VOLKSWAGEN PASSAT VARIANT: 1KRL065

Vinnumber:	WVWZZZ3CZGE003527	Versionname:	1.6 TDI VARIANT COMFORTLINE
First Registrationdate:	16/06/2015	Fiscalpower:	
Expertise Mileage:	125094	Power Kw:	88
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4402
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/95 V LightMetal			
Summer tyres:	Fr.L.	Kleber: 3 mm	Fr.R.
	Re.L.	Kleber: 4 mm	Re.R.
			Kleber: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	318,35
Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Rear window, Scratch(es), E - Replace	0,00
---------------------------------------	------



Windscreen, Scratch(es), E - Replace	0,00
--------------------------------------	------

