



AUDI A4 AVANT: 1FAY738			
Vinnumber:	WAUZZZ8K6DA240691	Versionname:	2.0 TDI 100KW
First Registrationdate:	14/05/2013	Fiscalpower:	
Expertise Mileage:	197000	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1408
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	DVD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	225/55/16/95 Y LightMetal		
	Fr.L.	Continental: 4 mm	Fr.R.
			Continental: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.
			Michelin: 4 mm

Assistance equipment	
Emergency spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0


Total cost ex VAT	2698,25
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Alloy rim F R, Scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20



Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	--------



Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Rear spoiler, Chemical polution, LI - Repair and paint (complete)	115,56




Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Scratch(es), E - Replace

487,20



Roof, Chemical polution, LI - Repair and paint (complete)

481,50





Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F L, Dent(s), LI - Repair and paint (complete) 115,56



Tailgate, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display