


VOLVO XC90: PK8178

Vinnumber:	YV1LFA4BCG1021501	Versionname:	2.0 D5 4WD GEARTRONIC INSCRIPTION 7PL.
First Registrationdate:	1/09/2015	Fiscalpower:	
Expertise Mileage:	163161	Power Kw:	165
Bodytype:	MPV	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2117
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Windows electric F	Seats electric F L
Windows electric R	Seats electric F R
Cruise Control	Central consol F
Steering wheel multifunctional	Luggage cover
Seats F heated	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Type of Tow bar
Type of GPS	Headlighting LED
Type of Lining	GPS big screen color
Type of climate control	Lining leather
	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	275/45/20/110 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			386,40
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			95,00





Protection plate M, Tear, E - Replace	74,00
---------------------------------------	-------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bonnet, Dent(s), PDR - Paintless dent repair	122,40
--	--------

