



VOLVO V60: 1JJR452

Vinnumber:	YV1FW8481F1250694	Versionname:	1.6 D2 SUMMUM
First Registrationdate:	6/01/2015	Fiscalpower:	
Expertise Mileage:	106119	Power Kw:	84
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4102
Maintenance:	BINNEN 7787KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Seats electric F L
GPS storage	Central consol F
GPS storage	Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	Tow bar removable
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/50/17/95 W LightMetal			
	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			190,00
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Seat cover F L, Worn, Acceptable

0,00



Backrest cover F L, Worn, Acceptable

0,00



Maintenance book, Missing, E - Replace

0,00



Bumper R, Scratch(es), Acceptable

0,00

