



|                                   |                          |              |                       |
|-----------------------------------|--------------------------|--------------|-----------------------|
| <b>VOLVO V60: 1JLG432</b>         |                          |              |                       |
| Vinnumber:                        | <b>YV1FW8481F1254640</b> | Versionname: | <b>1.6 D2 KINETIC</b> |
| First Registrationdate:           | <b>16/01/2015</b>        | Fiscalpower: |                       |
| Expertise Mileage:                | <b>90145</b>             | Power Kw:    | <b>84</b>             |
| Bodytype:                         |                          | Body color   | <b>Grey</b>           |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>        |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b>      |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>             |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>2305</b>           |
| Number of doors                   | <b>5</b>                 |              |                       |
| Number of seats                   | <b>5</b>                 |              |                       |
| Number head rests                 | <b>5</b>                 |              |                       |
| Rims summer                       | <b>Aluminium</b>         |              |                       |
| Category                          | <b>Passenger Car</b>     |              |                       |
| Oil level                         | <b>OK</b>                |              |                       |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                       |

|                                |                              |                  |                   |
|--------------------------------|------------------------------|------------------|-------------------|
| <b>Options</b>                 |                              |                  |                   |
| Radio CD                       |                              | Central consol F |                   |
| Windows electric F             |                              | Luggage cover    |                   |
| Windows electric R             |                              | Type of Tow bar  | <b>No Tow bar</b> |
| Cruise Control                 |                              |                  |                   |
| Steering wheel multifunctional |                              |                  |                   |
| Radio multimedia               |                              |                  |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                  |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                  |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                  |                   |
| Type of climate control        | <b>Autom climate control</b> |                  |                   |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                                     |           | Lighting            | <b>OK</b>  |
|                                     |           | Wiperblades         | <b>OK</b>  |

|                |                           |                |       |                |
|----------------|---------------------------|----------------|-------|----------------|
| Degree of wear |                           |                |       |                |
| Summer tyres:  | 205/60/16/96 H LightMetal |                |       |                |
|                | Fr.L.                     | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
|                | Re.L.                     | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

|                                          |            |            |            |
|------------------------------------------|------------|------------|------------|
| <b>Assistance equipment</b>              |            |            |            |
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|                                        |       |
|----------------------------------------|-------|
| Total cost ex VAT                      | 95,00 |
| Bumper R, Scratch(es), Acceptable      | 0,00  |
| <i>No pictures to display</i>          |       |
| Bumper R, Scratch(es), Acceptable      | 0,00  |
| <i>No pictures to display</i>          |       |
| Alloy rim F L, Scratch(es), Acceptable | 0,00  |
| <i>No pictures to display</i>          |       |

No pictures to display

|                                   |      |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                        |      |
|----------------------------------------|------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
|----------------------------------------|------|

No pictures to display

|                                                              |       |
|--------------------------------------------------------------|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--------------------------------------------------------------|-------|

