



**RENAULT TRAFIC: CU4386**

Vinnumber:	<b>WF13FL01853809627</b>	Versionname:	<b>1.6 DCI 84KW EXTRA LWB 2.9T</b>
First Registrationdate:	<b>8/12/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>154255</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV16</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Windows electric F		Central consol F	
Radio multimedia		Rear parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>	Type of Tow bar	<b>No Tow bar</b>
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/65/16/105 T LightMetal</b>			
Winter tyres:	Fr.L.	<b>Other: 3 mm</b>	Fr.R.	<b>Other: 3 mm</b>
	Re.L.	<b>Other: 8 mm</b>	Re.R.	<b>Other: 8 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

<b>Total cost ex VAT</b>	<b>3048,39</b>
<b>Bumper F, Scratch(es), Smart repair</b>	<b>110,64</b>





Bumper corner R R, Scratch(es), Smart repair

110,64




Rearview mirror glass R, Broken, E - Replace

13,50



Trunk door R L, Dent(s) and scratch(es), It - Spot repair

139,56



Bumper corner R L, Scratch(es), Smart repair

110,64



Door moulding Lower R R, Scratch(es), E - Replace


91,50



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76





Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), Smart repair 110,64



Outer door handle R R, Broken, E - Replace 64,00



Rearview mirror R complete, Broken, E - Replace 138,00



Seat cover F L, Worn, Acceptable 0,00



Wing trim R R, Scratch(es), E - Replace 69,00





Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15




Door F R, Scratch(es), LI - Repair and paint (complete)

238,76



Windscreen, Stone chip(s), Windscreen repair

58,80



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Door moulding Lower R L, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Door R R, Scratch(es), Acceptable

0,00

Rearview mirror housing L, Scratch(es), Smart repair

110,64



Bonnet, Dent(s), LI - Repair and paint (complete)

217,56



Trunk door R R, Dent(s) and scratch(es), It - Spot repair

115,56



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)

409,13

