



**AUDI A3 SPORTBACK: 1LLG069**

Vinnumber:	<b>WAUZZZ8V2GA059022</b>	Versionname:	<b>1.6 TDI ULTRA ATTRACTION SPORTBACK</b>
First Registrationdate:	<b>19/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>182835</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3727</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------


Total cost ex VAT	<b>1292,82</b>
-------------------	----------------

Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>
---	---------------





Roof, Chemical polution, Acceptable 0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 404,20



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 316,18



Bumper F, Dent(s) and scratch(es), It - Spot repair 0,00



Alloy rim F L, Scratch(es), I - Repair 100,00



Luggage space cover, Scratch(es), Smart repair 110,64



Alloy rim R R, Scratch(es), Acceptable 0,00



Ignition key, Missing, E - Replace 150,00

