



LU AUDI a3 Limousine: UK8754

Vinnnumber:	WAUZZZ8V4J1016700	Versionname:	1.0 TFSI 85kW
First Registrationdate:	4/10/2017	Fiscalpower:	
Expertise Mileage:	14757	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	2713
Maintenance:	15.300 KM OU 2 JOURS		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
GPS storage		Rear parking sensors	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 W LightMetal			
Summer tyres:	Fr.L.	Fr.R.	Goodyear: 6 mm
	Re.L.	Re.R.	Goodyear: 8 mm

Assistance equipment


Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 987,95

Door R R, Scratch(es), Acceptable 0,00

No pictures to display


Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 307,80



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Bad repair, LI - Repair and paint (complete) 318,35



Registration Document, Missing, E - Replace 150,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display