



**MERCEDES A: XA4869**

Vinnumber:	<b>WDD1770031N005670</b>	Versionname:	<b>A 180 d Launch Edition</b>
First Registrationdate:	<b>16/07/2018</b>	Fiscalpower:	
Expertise Mileage:	<b>49538</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3308</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	<b>Headlighting LED</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather and alcantara</b>
Type of climate control	<b>Autom climate control</b>
Sport seats	<b>No Tow bar</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/40/19/93 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

**Assistance equipment**


Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>1559,76</b>
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>





Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Rearview mirror R complete, Scratch(es), Le - Replace and paint

283,00



Bumper F, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18

