



MERCEDES CLA: 1LEN574

Vinnumber:	WDD1173081N284752	Versionname:	2.1 CLA 200 CDI URBAN
First Registrationdate:	7/09/2015	Fiscalpower:	
Expertise Mileage:	126964	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1704
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/40/18/92 Y LightMetal				
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1510,29
Bumper F, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)			95,00



Roof pillar L, Chemical polution, LI - Repair and paint (complete) 220,18



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Tailgate, Chemical polution, LI - Repair and paint (complete) 301,68



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00





Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00

