



BMW 4 GRAN COUPE: 1LLJ299

Vinnumber:	WBA4E910X0G391040	Versionname:	2.0 420D (120KW) GRAN COUPE
First Registrationdate:	20/10/2015	Fiscalpower:	
Expertise Mileage:	101494	Power Kw:	120
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1311
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/94 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 941,93

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display
Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display
Ignition key, Missing, E - Replace 150,00

No pictures to display

No pictures to display

Protection plate M, Deformed / Strained, E - Replace

74,00



Bonnet, Scratch(es), LI - Repair and paint (complete)

348,09



Roof, Chemical pollution, LI - Repair and paint (complete)

0,00



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Chemical pollution, LI - Repair and paint (complete)

369,84

