



## AUDI A6: 1KBBV920

Vinnumber:	<b>WAUZZZ4G1FN074156</b>	Versionname:	
First Registrationdate:	<b>27/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>54668</b>	Power Kw:	<b>235</b>
Bodytype:		Body color:	<b>Light Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>4 Wheel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4424</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Seats electric F L	
GPS storage	<b>HD</b>	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

<b>255/40/20/101 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Pirelli: 5 mm</b>	Fr.R.	<b>Pirelli: 5 mm</b>
	Re.L.	<b>Pirelli: 4 mm</b>	Re.R.	<b>Pirelli: 4 mm</b>

## Assistance equipment

Emergency spare wheel	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Total cost ex VAT	1454,96
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16



Bonnet, Stone chip(s), Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display


Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Tear, E - Replace 408,00



Roof, Chemical polution, LI - Repair and paint (complete) 577,80



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing moulding F R, Scratch(es), LI - Repair and paint 408,00



Wing trim R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper F, Scratch(es), Acceptable

0,00

*No pictures to display*

Door R L, Scratch(es), Acceptable

0,00

*No pictures to display*