



TOYOTA YARIS: 1PRC011

Vinnumber:	VNKKD3D310A268964	Versionname:	1.5 VVT-I HYBRID BUSINESS PLUS AUTO
First Registrationdate:	26/08/2016	Fiscalpower:	
Expertise Mileage:	86843	Power Kw:	54
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	1127
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	175/65/15/84 H LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	-----	------	-----

Total cost ex VAT	169,17
Alloy rim R L polished, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Stone chip(s), Acceptable	0,00
No pictures to display	
Alloy rim F L polished, Scratch(es), Acceptable	0,00

No pictures to display

Rearview mirror housing L, Broken, Le - Replace and paint 169,17



Door panel R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Repaired, Acceptable 0,00



Wing R R, Repaired, Acceptable 0,00



Rocker panel inner F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Repaired, Acceptable 0,00

