



**RENAULT CLIO: 1LNS481**

|                                    |                          |              |                                      |
|------------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber:                         | <b>VF15R0J0A54118300</b> | Versionname: | <b>1.5 ENERGY DCI 90E EXPRESSION</b> |
| First Registrationdate:            | <b>30/10/2015</b>        | Fiscalpower: |                                      |
| Expertise Mileage:                 | <b>101535</b>            | Power Kw:    | <b>66</b>                            |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Grey</b>                          |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                       |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>                         |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                            |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2613</b>                          |
| Number of doors:                   | <b>5</b>                 |              |                                      |
| Number of seats:                   | <b>5</b>                 |              |                                      |
| Number head rests:                 | <b>5</b>                 |              |                                      |
| Rims summer:                       | <b>Steel</b>             |              |                                      |
| Category:                          | <b>Passenger Car</b>     |              |                                      |
| Oil level:                         | <b>OK</b>                |              |                                      |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                      |

**Options**

|                                |                               |                      |  |
|--------------------------------|-------------------------------|----------------------|--|
| GPS storage                    |                               | Luggage cover        |  |
| GPS storage                    | <b>HD</b>                     | Rear parking sensors |  |
| Windows electric F             |                               |                      |  |
| Steering wheel multifunctional |                               |                      |  |
| Radio multimedia               |                               |                      |  |
| Type of headlighting           | <b>Headlighting Halogen</b>   |                      |  |
| Type of GPS                    | <b>GPS big screen color</b>   |                      |  |
| Type of Lining                 | <b>Lining fabrics</b>         |                      |  |
| Type of climate control        | <b>Manual climate control</b> |                      |  |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                             |                       |       |                       |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
|               | <b>185/65/15/92 V Steel</b> |                       |       |                       |
| Summer tyres: | Fr.L.                       | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|               | Re.L.                       | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>328,44</b> |
|-------------------|---------------|

|  |              |
|--|--------------|
| Wing R L, Dent(s), PDR - Paintless dent repair | <b>63,00</b> |
|--|--------------|



|   |               |
|---|---------------|
| Bumper R, Dent(s), LI - Repair and paint (complete) | <b>265,44</b> |
|---|---------------|

