



MERCEDES B: 1KBL700

Vinnumber:	WDD2462121J315832	Versionname:	1.5 B 180 CDI BLUEEFF STYLE EDITION
First Registrationdate:	25/03/2015	Fiscalpower:	
Expertise Mileage:	68329	Power Kw:	80
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3810
Maintenance:	A IN 339 DAGEN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Summer tyres:	Fr.L.	Yokohama: 5 mm	Fr.R.	Yokohama: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	414,09
Bumper F R, Scratch(es), It - Spot repair	115,56



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Compressor, Missing, E - Replace 0,00



Tyre repair kit, Missing, E - Replace 210,53



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 25,00



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Door R L, Dent(s), PDR - Paintless dent repair 63,00

