



| | | | |
|----------------------------------|--------------------------|--------------|---------------------|
| BMW 2 GRAN TOURER: KT5142 | | | |
| Vinnumber: | WBA2D510X0P786581 | Versionname: | 220i (141kW) |
| First Registrationdate: | 28/03/2017 | Fiscalpower: | |
| Expertise Mileage: | 44791 | Power Kw: | 141 |
| Bodytype: | MPV | Body color: | Silver |
| Gearbox: | MAN 6 VIT | Paint type: | Metallic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Petrol | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2719 |
| Number of doors: | 5 | | |
| Number of seats: | 7 | | |
| Number head rests: | 7 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Options | | | |
| Windows electric F | | Sun Roof electric | |
| Windows electric R | | Panoramic roof | |
| Cruise Control | | Central consol F | |
| Steering wheel multifunctional | | Luggage cover | |
| Radio multimedia | | Front parking sensors | |
| Type of headlighting | Headlighting Halogen | Rear parking sensors | |
| Type of GPS | GPS big screen color | Type of Tow bar | No Tow bar |
| Type of Lining | Lining Alcantara | | |
| Type of climate control | Autom climate control | | |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| | | | | |
|-----------------------|----------------------------------|-----------------------|-------|-----------------------|
| Degree of wear | | | | |
| | 225/45/18/91 W LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

| | |
|--|--------|
| Assistance equipment | |
| Total cost ex VAT | 285,00 |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |





Alloy rim F L polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display