


VOLKSWAGEN Passat: 1WSL265

Vinnumber:	WVWZZZ3CZEE048751	Versionname:	PASSAT VAR Trendline BM 105PK
First Registrationdate:	25/09/2013	Fiscalpower:	
Expertise Mileage:	192621	Power Kw:	77
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2127
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/94 V Steel			
Summer tyres:	Fr.L.	Fr.R.	Michelin: 4 mm
	Re.L.	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	526,91
Door F R, Dent(s), PDR - Paintless dent repair	63,00



Wheel cover R L, Scratch(es), Acceptable	0,00
No pictures to display	
Rocker panel inner R R, Dent(s), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Scratch(es), It - Spot repair	115,56



Windscreen, Scratch(es), Acceptable	0,00
No pictures to display	
Wheel cover F R, Scratch(es), E - Replace	30,00



Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------

