



BMW 3 TOURING: 1LJJ738

Vinnumber:	WBA8L71090K555631	Versionname:	2.0 316D (85KW) TOURING
First Registrationdate:	5/10/2015	Fiscalpower:	
Expertise Mileage:	161236	Power Kw:	85
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 18000 KM	Parking lot:	2427
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1123,08

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Dent(s) and scratch(es), Acceptable

0,00



Rearview mirror basis L, Scratch(es), Smart repair

110,64



Door F L, Not original part, P - Check

0,00



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Rocker panel inner R R, Scratch(es), Forfeit

125,00



Sunblind R, Broken, E - Replace

150,00



Bumper R, Scratch(es), It - Spot repair

115,56



Bumper F, Scratch(es), LI - Repair and paint (complete)

244,80

Bumper L, Scratch(es), L - repair and paint (complete)

211,00



Seat cover R, Stain, Cleaning

25,00



Wing F L, Dent(s) and scratch(es), Acceptable

0,00

