



AUDI A3: 1HXH772

Vinnumber:	WAUZZZ8V9FA063793	Versionname:	A3 SB Ultra Attraction 110PK
First Registrationdate:	21/10/2014	Fiscalpower:	
Expertise Mileage:	80197	Power Kw:	81
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4333
Maintenance:	BINNEN 9500 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Kleber: 7 mm	Re.R.	Kleber: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1834,36
Seat cover R R, Stain, Cleaning	25,00



Bumper F, Broken, Le - Replace and paint

735,00



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), It - Spot repair

115,56



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Seat cover F R, Stain, Cleaning

25,00



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Door F R, Bad repair, Acceptable

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper grille, Broken, E - Replace

373,80



Door R R, Bad repair, Acceptable

0,00



Rear window, Scratch(es), E - Replace

370,00

