



FORD S Max: 1JFC366			
Vinnumber:	WF05XXGBWSEA11427	Versionname:	S-MAX Titanium Style St/St DPF 115PK
First Registrationdate:	1/12/2014	Fiscalpower:	
Expertise Mileage:	191038	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3110
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Type of headlighting	Headlighting LED	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	Tow bar removable
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/98 Y LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1304,74
Wing F L, Chemical polution, Chemical cleaning			25,00





Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror L complete, Broken, Le - Replace and paint 259,00



Door F R, Dent(s), PDR - Paintless dent repair 63,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 232,06



Floor covering F L, Hole, E - Replace 240,00



Wing R L, Dent(s), PDR - Paintless dent repair 63,00



Wheel bolt cover F R, Missing, E - Replace 20,00



Wheel bolt cover R R, Missing, E - Replace 20,00



Backrest cover F L, Worn, Acceptable 0,00



Roof pillar L, Chemical polution, Chemical cleaning 25,00



Seat cover F R, Worn, Acceptable 0,00



Wheel bolt cover F R, Missing, E - Replace 20,00



Door R L, Dent(s), PDR - Paintless dent repair 63,00



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Door F L, Dent(s), LI - Repair and paint (complete) 254,68

