


BMW 3 TOURING: 1LEH716

Vinnumber:	WBA8L71000K555310	Versionname:	2.0 316D (85KW) TOURING
First Registrationdate:	4/09/2015	Fiscalpower:	
Expertise Mileage:	113065	Power Kw:	85
Bodytype:		Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 28000 KM	Parking lot:	3501
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 W LightMetal				
Summer tyres:	Fr.L.	Hankook: 4 mm	Fr.R.	Hankook: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1153,90
Alloy rim R R, Scratch(es), Acceptable	0,00

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Tyre repair kit, Missing, Repair/replace (lump sum)

35,00



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Outer backrest protection L, Scratch(es), Smart repair

110,64




Door frame R R, Dent(s), Acceptable

0,00

No pictures to display

Bonnet, Chemical pollution, LI - Repair and paint (complete)

290,08



Backrest cover F L, Worn, P - Check

0,00



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), Acceptable

0,00

No pictures to display


Door panel R L, Tear, E - Replace

114,00



Interior, Dirty, Cleaning

30,00



Grill frame, Broken, E - Replace

59,40



Door frame R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Chemical polution, LI - Repair and paint (complete)

220,18



Wing R R, Dent(s), PDR - Paintless dent repair

82,80

