


BMW 1 HATCH: 1KJX581

Vinnumber:	WBA1C910X0P991324	Versionname:	1.6 116D EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	18/05/2015	Fiscalpower:	
Expertise Mileage:	154445	Power Kw:	85
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1722
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	861,75
Door F L, Dent(s), LI - Repair and paint (complete)	318,35



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wing F L, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), E - Replace 235,20



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Bumper F, Repaired, Acceptable 0,00

No pictures to display